

Eclipse Datalog Drill Report

Project: V1-5 kuni Järvekalda De50
Address: Valma

Customer:
Address:


Contact:
Phone:

Eclipse S/N: 5022

Contractor: Gabariit OÜ
Address: Tedre 30
Tallinn

Contact: Rein Koor
Phone: +3725655225

Date: 29.08.2011
Time:



Rod	xDist (m)	Pitch (%)	Depth (m)	iDepth (m)	Rel. Elev. (m)	Type
0	0.00	-31.4		0.00		p
1	3.80	-33.7		-1.24		p
2	6.67	-27.9	1.81	-2.12	-0.31	
3	9.62	-9.4	2.11	-2.67	-0.55	
4	12.62	-0.8	2.17	-2.82	-0.65	
5	15.62	1.0	2.12	-2.81	-0.69	
6	18.62	-3.9	2.15	-2.86	-0.70	
7	21.61	-3.8	2.28	-2.97	-0.69	
8	24.61	0.8	2.26	-3.02	-0.75	
9	27.61	-0.6	2.22	-3.02	-0.79	
10	30.61	2.1	2.12	-2.99	-0.87	
11	33.61	-0.6	2.01	-2.97	-0.96	
12	36.61	-1.3	2.00	-3.00	-1.00	
13	39.61	-3.3	2.05	-3.07	-1.02	
14	42.61	-2.8	2.15	-3.16	-1.01	
15	45.61	-0.5	2.17	-3.21	-1.04	
16	48.61	-0.5	2.13	-3.22	-1.09	
17	51.61	-3.0	2.19	-3.27	-1.08	
18	54.61	1.2	2.24	-3.30	-1.06	

This report contains a log of data taken by above-ground locating equipment during below-ground drilling. Because the accuracy of such data can be adversely affected by environmental and operational factors, the data does not necessarily provide an accurate representation of actual site conditions.

Rod	xDist (m)	Pitch (%)	Depth (m)	iDepth (m)	Rel. Elev. (m)	Type
19	57.61	1.2	2.19	-3.27	-1.08	
20	60.61	0.3	2.17	-3.25	-1.08	
21	63.61	2.0	2.10	-3.21	-1.11	
22	66.61	-5.3	2.16	-3.26	-1.10	
23	69.61	-0.5	2.22	-3.35	-1.13	
24	72.61	-0.1	2.19	-3.36	-1.17	
25	75.61	0.8	2.15	-3.35	-1.20	
26	78.61	0.8	2.07	-3.32	-1.25	
27	81.61	1.7	2.00	-3.29	-1.29	
28	84.61	-1.9	2.00	-3.29	-1.29	
29	87.61	-1.2	2.06	-3.34	-1.27	
30	90.61	-1.5	2.06	-3.38	-1.32	
31	93.61	-1.5	2.00	-3.42	-1.42	
32	96.61	1.5	1.91	-3.42	-1.51	